


FUR- 1707 Installation diagram of file cabinet





Eccentric installation principle


























Door plank of adjustment

The crack of the door is too large





As shown, the screw the screwdriver points to, Itmoves the door from side to side, Clockwise rotation is to adjust the door panel to the middle

The gap between door panel and side panel is too large





As shown in the figure, loosen the screw pointed by the screwdriver, push the door panel in or out and tighten it, Solve the above roblems











As shown in the figure, loosen the screw pointed by the screwdriver, push the lower door panel and hinges up and tighten the screws push the higher door panel and hinges down and tighten the screws.